

CORRES. CONTROL

LTR. NO.

Originator Ltr Log #

JEL-178-98

97 - RF -

| DIST. | LTR | ENC |
|----------------|-----|-----|
| BENSON, C.A. | | |
| CARMEAN, C.H. | | |
| CRAWFORD, A.C. | | |
| DAWSON, D. | | |
| EDWARDS, J.D. | | |
| FINOLEY, M.E. | | |
| FITZ, R.C. | | |
| GUINN, L.A. | | |
| HUGHES, F.P. | | |
| REED, A.B. | | |
| TYSON, A.M. | | |
| WAGNER, M.J. | | |
| WHEELER, M. | | |

b1
b2
b3
b4
b5
b6
b7c
b7e
b7f
b7g
b7h
b7i
b7j
b7k
b7l
b7m
b7n
b7o
b7p
b7q
b7r
b7s
b7t
b7u
b7v
b7w
b7x
b7y
b7z

| | | |
|--------------|----------|---|
| RMRS RECORDS | X | ✓ |
| w/o | IDM4.mdb | |

| | |
|------------|--|
| RF CORRES. | |
| CONTROL | |
| TRAFFIC | |
| PATS/T130G | |

| | |
|-----------------|--|
| CLASSIFICATION: | |
| UCNI | |
| UNCLASSIFIED | |
| CONFIDENTIAL | |
| SECRET | |

AUTHORIZED CLASSIFIER

SIGNATURE:

Date: 10-29-98

IN REPLY TO RF CC NO.:

| | |
|---------------------|--|
| ACTION ITEM STATUS: | |
| PARTIAL/OPEN | |
| CLOSED | |

LTR APPROVALS:

ORIG. & TYPIST INITIALS:
RSL:AW

RF-46469(Rev.1/97)



Rocky Mountain
Remediation Services, L.L.C.
... protecting the environment

Flats Environmental Technology Site

bx 464
1, Colorado 80402-4064
(303) 966-7000



000101387

October 29, 1998

Colburn Kennedy
Waste & Remediation Operations
Building 130
Kaiser-Hill, L.L.C.

INVESTIGATIVE DERIVED MATERIAL (IDM) DRUMS & SUPPORTING DATA FOR BACKFILLING THE T-1 TRENCH - JEL-178-98

The purpose of this letter is to supplement the information contained in my last correspondence (JEL-175-98) regarding placement of IDM in Trench 1. In addition to the 977 drums specifically listed for backfilling in the last correspondence, additional drums were researched that fell into the following categories:

IDM drums with Volatile Organic Compounds (VOC) results but no radiological analyses (750 drums):

- Locations were overlaid with plutonium isopleths to determine qualitative probability of radiological contaminant presence (Figure 1).
- Boreholes/well locations were reviewed by Subject Matter Experts (SME) for potential radionuclide presence.

IDM drums with radiological results but no VOC analyses (135 drums):

- Uranium isotopic results were reverified due to the proximity to OU-5.
- Boreholes/well locations were reviewed by SMEs for potential VOC contaminant presence (Figure 2).
- Locations were overlaid with VOC groundwater plume isopleths to determine the qualitative probability of VOC presence.

Based on these evaluations, the drums listed in Tables 1 and 2 are recommended for backfill in Trench-1. The drums listed in Table 3 were disqualified. The rationale for these recommendations is described below.

All drums contained in Table 1 were derived from the locations in Figure 1 that are outside the 50 pCi/g area, i.e., from locations where surface concentrations are less than 50 pCi/g. Recall that maximum actinide concentrations are historically at the surface (~90% of activity is within the top 2" of soil), with concentrations decreasing in depth -- well below the RFCA Tier II action level of 212 pCi/g for ^{239,240}Pu. Therefore, drum contents that correlate to these locations are likely to have lower actinide concentrations than those indicated by the associated isopleth values. Drums/locations shown as "disqualified" in Table 3 were in areas greater than 50 pCi/g.

ADMIN REC'D

1/8

1108-A-00078

Colburn Kennedy
October 29, 1998
JEL-178-98
Page 2 of 3

All drums contained in Table 2 were derived from the locations in Figure 2 that are outside the "100x MCL" area, i.e., from locations where surface plutonium concentrations are less than 100x MCLs. Note that the plume values represent groundwater concentrations whereas drum contents consist of soils at the listed locations and not the groundwater plume. Based on locations of the plume sources, soil concentrations above the plumes are likely less than concentrations in the plume.

The attached data set (IDM4.mdb, an MS ACCESS file) contains two final correlation tables "d-pass-VOC-detailT" and "d-pass-Rad-detailT," both of which were derived from the master data set "oct19pull" taken directly from the RMRS Soil/Water Database (SWD). The tables constitute reports, or "cross-walks," that correlate IDM drums with locations, samples, analytes, and results. Consistent with the previous table of 977 drums, the enclosed final correlation tables were derived through queries that filtered the data relative to the following parameters or processes:

- Solid matrices only (i.e., soils, no liquids).
- Omission of any Rejected data (per the RFETS data validation process).
- Comparison of ALL sample results w/ RFCA Action Levels, to ensure disqualification of drums not appropriate for return to the trench.
- Sorting by DRUM identification number, in ascending order.

In summary, the drums with analytical and radiochemistry results listed in the attached database (IDM4.mdb) are acceptable for "put-back" into Trench-1 based on the data evaluations described above. The limited results coupled with other site environmental data indicate that the associated drum contents are suitable for put-back into Trench-1. Drums in Table 1 have VOC results related to the IDM that do not exceed RFCA Action Levels; where all VOC results, for the contaminants of concern listed below, were individually compared with RFCA Action Levels to determine acceptance or rejection of each individual drum. Drums were considered acceptable where 1) analytical results existed for the drum, AND 2) the associated results were below RFCA Tier II action levels (note: only Tier I Action Levels were available for VOCs in solids -- Tier II action levels have yet to be established). Acceptance criteria for drums/data results are given below. Likewise, drums in Table 2 have actinide results related to IDM that do not exceed RFCA Action Levels.

PASS/FAIL CRITERIA

RADIONUCLIDES (Rads)

(Table ES-1, Tier II Soil Action Levels {Industrial Area Office Worker}, RFCA Attachment 5, October 31, 1996)

| | <u>Solids (pCi/kg)</u> |
|------------|------------------------|
| U-233,234 | 307 |
| U-235 | 24 |
| U-238 | 103 |
| Pu-239,240 | 252 |
| Am-241 | 38 |

Colburn Kennedy
October 29, 1998
JEL-178-98
Page 3 of 3

VOLATILE ORGANIC COMPOUNDS (VOCs)

(Table 4, Tier I Subsurface Soil Action Levels, RFCA Attachment 5, July 19, 1996)

| | <u>Solids (ug/kg)</u> |
|--|-----------------------|
| Tetrachloroethene (PCE) | 11,500 |
| Trichloroethene (TCE) | 9,270 |
| Carbon Tetrachloride (CCl ₄) | 11,000 |

Note that significant figures in the tables, unaltered from the database source, should generally be limited to a resolution of 0.01 pCi/g for isotopic results and 0.005 mg/kg for VOCs.

Current status on dispositioning of the IDM drums is as follows:

Drums Recommended for Placement in Trench 1:

- 977 drums with both radiological and VOC results below RFCA Action Levels (see JEL-175-98).
- 502 drums with VOC results below RFCA Tier 1 Action Levels that correlate to locations likely to have actinide concentrations less than 50 pCi/g (Table 1).
- 122 drums with radiological data below RFCA Tier II Action Levels that correlate to locations likely to have VOC concentrations less than 100x MCLs. (Table 2).

Overall Project Status:

- 1,601 drums are acceptable for return to the trench.
- 261 drums have been rejected based on associations to locations.
- Approximately 638 drums remain to be correlated to sample results.

As stated in my previous correspondence, we will continue to investigate potential links for the 638 remaining drums up to 40 hours of effort.

If you have additional questions or concerns please contact me at extension 4842.



John E. Law
Director
Closure Management Division

RSL/aw

Attachments:
As Stated

cc:

Lane Butler w/o IDM4.mdb
Tom Greengard w/o IDM4.mdb
Alan Rodgers w/o IDM4.mdb

| <u>DRUM</u> |
|-------------|-------------|-------------|-------------|-------------|-------------|-------------|
| 1262 | 3240 | 3324 | 3465 | 3597 | 4067 | 675 |
| 1263 | 3241 | 3325 | 3466 | 3598 | 4068 | 682 |
| 1264 | 3244 | 3326 | 3473 | 3602 | 4069 | 684 |
| 1265 | 3245 | 3327 | 3474 | 3603 | 407 | 686 |
| 1266 | 3246 | 3328 | 3475 | 3604 | 4070 | 693 |
| 1267 | 3247 | 3329 | 3476 | 3605 | 4208 | 698 |
| 1268 | 3248 | 3330 | 3477 | 3610 | 4209 | 715 |
| 160 | 3249 | 3331 | 3478 | 3611 | 4210 | 731 |
| 171 | 325 | 3332 | 3479 | 366 | 4211 | 805 |
| 176 | 3250 | 3333 | 348 | 3664 | 4212 | 806 |
| 180 | 3251 | 3342 | 3480 | 3665 | 4214 | 807 |
| 184 | 3252 | 3343 | 3481 | 3666 | 429 | 808 |
| 187 | 3253 | 3344 | 3482 | 3667 | 431 | 809 |
| 203 | 3258 | 3345 | 3483 | 368 | 443 | 810 |
| 204 | 3259 | 3346 | 3484 | 370 | 444 | 815 |
| 206 | 3260 | 3347 | 3485 | 372 | 447 | 816 |
| 208 | 3261 | 3348 | 3486 | 379 | 450 | 817 |
| 209 | 3262 | 3349 | 3487 | 3814 | 452 | 818 |
| 211 | 3263 | 335 | 3488 | 3815 | 453 | 819 |
| 212 | 3264 | 3350 | 3489 | 3816 | 454 | 820 |
| 223 | 3265 | 3351 | 349 | 3817 | 456 | 821 |
| 226 | 3266 | 3352 | 3490 | 3818 | 457 | 823 |
| 228 | 3267 | 3357 | 3503 | 3819 | 460 | 824 |
| 2310 | 3268 | 3358 | 3504 | 3822 | 462 | 825 |
| 2311 | 3269 | 3359 | 3505 | 3824 | 464 | 826 |
| 2312 | 327 | 3360 | 3506 | 3826 | 465 | 827 |
| 2313 | 3270 | 337 | 3507 | 3827 | 466 | 828 |
| 2317 | 3271 | 3374 | 3508 | 3828 | 467 | 829 |
| 2318 | 3272 | 3375 | 3509 | 3850 | 469 | 830 |
| 2319 | 3273 | 3376 | 3510 | 3851 | 473 | 831 |
| 232 | 3274 | 3377 | 3511 | 3852 | 475 | 832 |
| 2320 | 3275 | 3378 | 3512 | 3853 | 478 | 833 |
| 2321 | 3276 | 3379 | 3537 | 3854 | 480 | 834 |
| 2322 | 3277 | 338 | 3538 | 3855 | 490 | 835 |
| 2323 | 3278 | 3380 | 354 | 3860 | 497 | 836 |
| 2324 | 3279 | 3381 | 3540 | 3861 | 498 | 837 |
| 2329 | 328 | 3382 | 3541 | 3862 | 500 | 838 |
| 233 | 3280 | 3383 | 3542 | 3863 | 501 | 841 |
| 234 | 3281 | 3384 | 3543 | 3864 | 504 | 842 |
| 2422 | 3282 | 3385 | 3544 | 3865 | 510 | 843 |
| 2423 | 3283 | 3386 | 3545 | 3866 | 518 | 844 |
| 2424 | 3284 | 3387 | 3546 | 3867 | 519 | 845 |
| 246 | 3289 | 3388 | 3547 | 3868 | 524 | 858 |
| 2608 | 3290 | 3389 | 3548 | 3871 | 527 | 859 |
| 2609 | 3291 | 3390 | 3549 | 3872 | 530 | 860 |
| 2615 | 3292 | 3391 | 3550 | 3873 | 542 | 941 |
| 2616 | 3293 | 3392 | 3555 | 3874 | 546 | 942 |
| 2642 | 3294 | 3393 | 3556 | 3879 | 551 | 944 |
| 2643 | 3295 | 340 | 3557 | 3880 | 553 | 949 |
| 2644 | 3296 | 341 | 3558 | 3881 | 560 | 950 |
| 265 | 3297 | 3412 | 3559 | 3882 | 562 | 951 |
| 279 | 3298 | 3413 | 356 | 3883 | 571 | 960 |
| 280 | 3299 | 3414 | 3560 | 3884 | 575 | |
| 283 | 3300 | 3423 | 3569 | 3885 | 576 | |
| 292 | 3305 | 3424 | 3570 | 3886 | 581 | |
| 3126 | 3306 | 3425 | 3571 | 3887 | 587 | |
| 3127 | 3307 | 3426 | 3572 | 3888 | 594 | |
| 3194 | 3308 | 3427 | 3573 | 389 | 597 | |
| 3195 | 3309 | 3428 | 3574 | 390 | 600 | |
| 3196 | 331 | 3429 | 3575 | 3900 | 607 | |
| 3197 | 3310 | 3430 | 3576 | 3901 | 609 | |
| 320 | 3311 | 3431 | 3577 | 3902 | 611 | |
| 3207 | 3312 | 3432 | 3580 | 3903 | 612 | |
| 3208 | 3313 | 3433 | 3581 | 3906 | 615 | |
| 321 | 3314 | 3434 | 3582 | 3907 | 616 | |
| 3214 | 3315 | 3435 | 3583 | 3908 | 625 | |
| 3215 | 3316 | 3436 | 3584 | 3909 | 627 | |
| 3216 | 3317 | 3437 | 3585 | 3910 | 642 | |
| 3217 | 3318 | 3438 | 359 | 3911 | 650 | |
| 3234 | 3319 | 3439 | 3591 | 3926 | 651 | |
| 3235 | 332 | 344 | 3592 | 3927 | 654 | |
| 3236 | 3320 | 3440 | 3593 | 393 | 658 | |
| 3237 | 3321 | 3462 | 3594 | 395 | 661 | |
| 3238 | 3322 | 3463 | 3595 | 396 | 673 | |
| 3239 | 3323 | 3464 | 3596 | 401 | 674 | |


| <u>DRUM</u> | <u>DRUM</u> | <u>DRUM</u> |
|-------------|-------------|-------------|
| 2275 | 3075 | 3176 |
| 2276 | 3076 | 3177 |
| 2277 | 3085 | 3178 |
| 2278 | 3086 | 3179 |
| 2279 | 3087 | 3180 |
| 2280 | 3088 | 3181 |
| 2281 | 3089 | 3182 |
| 2282 | 3090 | 3183 |
| 2283 | 3095 | 3184 |
| 2284 | 3096 | 3185 |
| 2285 | 3098 | 3186 |
| 2286 | 3099 | 3187 |
| 2289 | 3100 | 3188 |
| 2290 | 3101 | 3189 |
| 2291 | 3102 | 3198 |
| 2296 | 3107 | 3199 |
| 2297 | 3108 | 3200 |
| 2299 | 3109 | 3201 |
| 2300 | 3110 | 3202 |
| 2302 | 3131 | 3209 |
| 2303 | 3132 | 3210 |
| 2305 | 3133 | 3211 |
| 2306 | 3134 | 3212 |
| 2307 | 3135 | 3242 |
| 2308 | 3136 | 3243 |
| 2826 | 3137 | 3622 |
| 2827 | 3138 | 3673 |
| 2895 | 3140 | 3674 |
| 2908 | 3141 | 3675 |
| 2909 | 3143 | 3676 |
| 2910 | 3161 | 3677 |
| 2911 | 3162 | 3678 |
| 2912 | 3164 | 3679 |
| 2913 | 3169 | 3770 |
| 3058 | 3170 | 3771 |
| 3059 | 3171 | 3772 |
| 3060 | 3172 | 3782 |
| 3062 | 3173 | 3783 |
| 3068 | 3174 | 3784 |
| 3069 | 3175 | 3785 |
| 3070 | | 3799 |

| <u>Location</u> | <u>DRUM</u> | <u>Location</u> | <u>DRUM</u> | <u>Location</u> | <u>DRUM</u> | <u>Location</u> | <u>DRUM</u> |
|-----------------|-------------|-----------------|-------------|-----------------|-------------|-----------------|-------------|
| 11791 | 481 | 21393 | 3337 | 22193 | 3445 | 22393 | 2839 |
| 12091 | 644 | 21393 | 3338 | 22193 | 3446 | 22393 | 2840 |
| 12091 | 670 | 21393 | 3339 | 22193 | 3447 | 22393 | 2841 |
| 12291 | 710 | 21393 | 3340 | 22193 | 3448 | 22393 | 2842 |
| 12291 | 718 | 21393 | 3341 | 22193 | 3449 | 22393 | 2851 |
| 12291 | 719 | 21393 | 3394 | 22193 | 3450 | 22393 | 2853 |
| 12991 | 1006 | 21393 | 3395 | 22193 | 3451 | 22393 | 3587 |
| 12991 | 1007 | 21393 | 3396 | 22193 | 3467 | 22393 | 3588 |
| 12991 | 1008 | 21393 | 3539 | 22193 | 3468 | 22393 | 3589 |
| 12991 | 1009 | 21493 | 3407 | 22193 | 3469 | 22393 | 3590 |
| 12991 | 977 | 21493 | 3416 | 22193 | 3470 | 22393 | 3623 |
| 12991 | 990 | 21493 | 3417 | 22193 | 3471 | 22393 | 3630 |
| 12991 | 991 | 21493 | 3418 | 22193 | 3472 | 22393 | 3631 |
| 13491 | 1443 | 21493 | 3441 | 22193 | 3495 | 22393 | 3632 |
| 13491 | 1445 | 21493 | 3442 | 22193 | 3496 | 22393 | 3637 |
| 13491 | 1448 | 21493 | 3443 | 22193 | 3497 | 22393 | 3661 |
| 13491 | 1451 | 21493 | 3444 | 22193 | 3498 | 22393 | 3662 |
| 13491 | 1452 | 21493 | 3456 | 22193 | 3499 | 22393 | 3663 |
| 13491 | 1502 | 21493 | 3457 | 22193 | 3500 | 22393 | 3669 |
| 13491 | 1503 | 21493 | 3458 | 22193 | 3501 | 22393 | 3670 |
| 13491 | 1504 | 21493 | 3459 | 22193 | 3502 | 22393 | 3671 |
| 13491 | 1505 | 21493 | 3460 | 22193 | 3513 | 22393 | 3672 |
| 13591 | 1527 | 21493 | 3461 | 22193 | 3514 | | |
| 13591 | 1545 | 21493 | 3525 | 22193 | 3515 | | |
| 13591 | 1567 | 21493 | 3526 | 22193 | 3516 | | |
| 13591 | 1569 | 21493 | 3527 | 22193 | 3517 | | |
| 13591 | 1570 | 21493 | 3528 | 22193 | 3518 | | |
| 13591 | 1571 | 21493 | 3529 | 22193 | 3519 | | |
| 21293 | 2847 | 21493 | 3530 | 22193 | 3520 | | |
| 21293 | 2848 | 21493 | 3531 | 22193 | 3521 | | |
| 21293 | 2849 | 21493 | 3532 | 22193 | 3522 | | |
| 21293 | 2850 | 21493 | 3533 | 22193 | 3523 | | |
| 21293 | 3612 | 21493 | 3535 | 22193 | 3524 | | |
| 21293 | 3613 | 21593 | 3370 | 22193 | 3561 | | |
| 21293 | 3614 | 21593 | 3371 | 22193 | 3562 | | |
| 21293 | 3615 | 21593 | 3372 | 22193 | 3563 | | |
| 21293 | 3616 | 21593 | 3373 | 22193 | 3564 | | |
| 21293 | 3617 | 21593 | 3398 | 22193 | 3565 | | |
| 21293 | 3618 | 21593 | 3399 | 22193 | 3566 | | |
| 21293 | 3620 | 21593 | 3400 | 22193 | 3567 | | |
| 21293 | 3649 | 21593 | 3401 | 22193 | 3568 | | |
| 21293 | 3650 | 21593 | 3404 | 22293 | 2833 | | |
| 21293 | 3689 | 21593 | 3405 | 22293 | 2834 | | |
| 21293 | 3691 | 21593 | 3406 | 22293 | 2835 | | |
| 21393 | 3190 | 21593 | 3491 | 22293 | 2836 | | |
| 21393 | 3191 | 21593 | 3492 | 22293 | 2837 | | |
| 21393 | 3192 | 21593 | 3493 | 22293 | 2838 | | |
| 21393 | 3193 | 21593 | 3494 | 22293 | 2863 | | |
| 21393 | 3203 | 21593 | 3551 | 22293 | 2864 | | |
| 21393 | 3204 | 21593 | 3552 | 22293 | 2865 | | |
| 21393 | 3205 | 21593 | 3553 | 22293 | 2866 | | |
| 21393 | 3206 | 21593 | 3554 | 22293 | 2867 | | |
| 21393 | 3218 | 21593 | 3606 | 22293 | 2868 | | |
| 21393 | 3219 | 21593 | 3607 | 22293 | 2869 | | |
| 21393 | 3220 | 21593 | 3608 | 22293 | 2870 | | |
| 21393 | 3221 | 22093 | 3690 | 22293 | 3536 | | |
| 21393 | 3222 | 22093 | 3692 | 22293 | 3619 | | |
| 21393 | 3223 | 22093 | 3693 | 22293 | 3633 | | |
| 21393 | 3224 | 22093 | 3694 | 22293 | 3634 | | |
| 21393 | 3225 | 22093 | 3695 | 22293 | 3635 | | |
| 21393 | 3226 | 22093 | 3696 | 22293 | 3636 | | |
| 21393 | 3227 | 22093 | 3697 | 22293 | 3681 | | |
| 21393 | 3228 | 22093 | 3710 | 22293 | 3682 | | |
| 21393 | 3229 | 22093 | 3711 | 22293 | 3683 | | |
| 21393 | 3254 | 22093 | 3712 | 22293 | 3720 | | |
| 21393 | 3255 | 22093 | 3736 | 22293 | 3721 | | |
| 21393 | 3256 | 22093 | 3747 | 22293 | 3722 | | |
| 21393 | 3257 | 22093 | 3748 | 22293 | 3728 | | |
| 21393 | 3301 | 22093 | 3749 | 22293 | 3729 | | |
| 21393 | 3302 | 22093 | 3750 | 22293 | 3730 | | |
| 21393 | 3303 | 22093 | 3751 | 22293 | 3731 | | |
| 21393 | 3304 | 22093 | 3752 | 22293 | 3735 | | |
| 21393 | 3334 | 22093 | 3766 | 22393 | 2821 | | |
| 21393 | 3335 | 22093 | 3767 | 22393 | 2822 | | |
| 21393 | 3336 | 22193 | 3397 | 22393 | 2823 | | |

Table 3. Disqualified IDM Drums, sorted by Location.

10/29/98

Figure 1
**IDM Drums
 with VOC Results (No Rad)
 Less than RFCA Action Levels
 Overlaid by
 PU-239/240 Isoplotbs (pCi/g)**



1 mile
 Scale = 1:20,000
 1 km
 Borehole Coordinates Projection
 StatePlane Colorado 2 FIPS
 Datum: NAD27

U.S. Department of Energy
 Rocky Flats Environmental Technology Site

RMRS
 Rocky Mountain
 Remediation Services, L.L.C.
 Environmental Information Systems Group
 Rocky Flats Environmental Technology Site
 P.O. Box 20000, Bldg. 100
 Golden, CO 80402-9944
 October 25, 1990

Figure 2
**IDM Locations
 with RAD Results (No VOC)
 Less than RFCA Tier II Action Levels
 Relative to VOC Plumes**

